In the Drawings:

Permission is requested to substitute corrected Fig. 5 in place of original Fig. 5 which is corrected as follows:

- (1)No. 402 has been corrected to 302
- (2) "Client interface (500)" in the box has been corrected to 'Client interface'; correct No. 502 has been entered outside the box.
- (3) "Set-top box (502)" in the box has been corrected to 'Set-top box'; correct No. 500 has been entered outside the box.

None of the above changes constitute new matter.

DE 0 1 2000 6

REPLACEMENT SHEET




Fig.5






Fig.5